

A photograph of a grassy embankment next to a concrete bridge structure. The embankment shows signs of erosion, with exposed soil and roots. A red surveying pole is visible on the slope.

